


arctic	PART - GROUP CHANGE NOTIFICATION				Bulletin no.	394	Date	23.01.2020
	Prepared by	MIHAI PURCAREANU			Signature 			
	Approved by	NICULIN CLEMENT DUMITRU						
	Copy to	Service		PE	MOP		Other	
		Prod. lines		QA			Other	

TECHNICAL EXPLANATION OF THE CHANGE	
Issue	Compressor replacement
Explanation: Replace compressor HTK 95 from Secop with TG1114YL from JIAXIPERA for F60312N A+ / F60312NE A+ (7518620003; 7518620001; 7517520001; 7517510003; 7517510002; 7517510001).	



Before January 2020



After January 2020

INFORMATION ABOUT THE PART CHANGES							
Spare part code	Old part(s)			Spare part code	New part(s)		
	Part name	Stok number	Rev.		Part name	Stok number	Rev.
30	Compressor HTK 95 AA	4221153300		30	Compressor TG1114YL	4361198500	B
2476	Equiped Supply Cord HTK 95 AA	4543619000		##	Equiped Supply Cord TG1114YL	4622789100	B

CODES EXPLANATION :


A-Old stocks can be used : Old and new parts are fully interchangeable

B- Old stocks can be used : Old parts can use only on old products and new parts can use only on new products.

C- Old stocks can not be used : New parts can use on old and new products

D-Old stocks can not be used : New parts can use only on new products

1-Performance/ 2- Production improvement/ 3-Safety / 4 -Material or dimension chang/ 5-Additional part/ 6- Part cancellation / 7- Alternative use

INFORMATION ABOUT THE PRODUCT CHANGES						Signature
No	Date	Brand	Model	Start modification from	Finished modif. at	
1	23.01.2020	-	F60312N/NE A+ 7518620003; 7518620001; 7517520001; 7517510003; 7517510002; 7517510001.	23.01.2020	28.01.2020	
2						
3						

F-1104-06