

	PART - GROUP CHANGE NOTIFICATION				Bulletin no	2007-069-YD-0	Date	05.11.2007	
	Prepared by	Tamer ULUER			Signature			Rev :	
	Approved by	Esra AKGÜN-Erdal GÜLCÜLER							
	Copy to	THD	✓	ABMİ - ÜPB	✓	ABMİ - MÜT		ABMİ - KGB	
		ABMİ - ÜGB	✓	ABMİ - MT		ABMİ - İGT		Customer	

#### TECHNICAL EXPLANATION OF THE CHANGE

##### Issue

##### Explanation

After the first installation or after any movement of a DW, the balance of the DWs must be obtained by adjusting the feet. The adjustment must be done with reference according to the base floor of the kitchen, not according to the top plate of the If the feet are adjusted with the top plate reference, if the floor is not proper, there might be misalignments of the outer door according to the top plate or side walls (not parallel) or even in some cases, mismatching of the door with the inner tub while closing.

The balance of the DW must be obtained by adjusting 4 feet of DW and measured by a "water gauge-balance". The parallelism of the door (right and left) with the top plate and side walls will be achieved after this balancing. In some models, you can use the hole in front of the DW (on the kick plate) by a screwdriver, for the purpose of adjusting the rear feet from the front.



#### INFORMATION ABOUT THE PART CHANGES

Ref	New part(s)		Ref	Old Part(s)		Code
	Part name	Stock number		Part name	Stock number	

##### CODE EXPLANATION :

**A**-Old stocks can be used; Old & new parts are fully interchangeable

**B**-Old stocks can be used; Old parts are interchangeable with old productions & new parts are interchangeable with new productions

**D**-Old stocks can not be used. New parts are interchangeable with new productions

**1**-Performance / **2**-Production improvement / **3**- Safety / **4**-Material or dimension change / **5**- Additional part / **6**-Part cancellation / **7**- Alternative use

#### INFORMATION ABOUT THE PRODUCT CHANGES

No	Date	Brand	Model	Started from	Finished at	Signature
1						
2						
4						
5						